



**Vehicle Running Report for the date 2021-01-19**

SL NO	Vehicle Number/Name	Driver Name	Vehicle IMEI	First Ignition	Last Ignition	Total Engine ON Time
1	801476		354017117821393	06:15:27	23:59:59	09:44:47
2	215942		359632103754146	08:00:01	17:33:05	07:50:54
3	217633		354017117835831	07:50:46	23:59:55	01:44:50
4	562208		354017117810768	06:32:39	21:24:50	02:15:04
5	790965		354017117442406	08:35:44	18:04:49	00:56:58
6	190621		354017117442315	08:18:08	17:14:45	03:17:32
7	172573		354017117442273	07:09:12	17:46:43	07:38:23
8	183378		354017117834651	07:54:00	23:39:57	03:11:20
9	537866		354017117442364	06:47:29	16:49:14	02:45:43
10	743752		354017117442182	06:31:58	18:21:57	03:42:24
11	167973		354017117815171	09:22:23	17:46:46	06:53:32
12	178363		359633100068779	00:00:00	23:31:09	04:07:38
13	783266		359633100055982	06:44:55	20:23:06	02:18:03
14	790972		359633100061287	04:40:04	19:29:21	05:52:46
15	801475		359633100061337	09:23:39	13:59:38	00:54:11
16	217981		354017117819488	07:29:42	18:02:16	02:14:19
17	435687		354017117833794	06:07:28	15:42:03	01:49:51
18	790973		359633100065726	02:30:37	21:53:29	00:30:30
19	793012		354017117442125	01:59:42	22:18:35	00:56:19
20	790978		359633100052567	07:11:26	17:07:18	02:38:55
21	792996		354017117836854	11:47:39	23:28:08	03:27:30
22	267530		359632109060860	07:46:08	19:57:23	01:16:08

## Vehicle Running Report for the date 2021-01-19

SL NO	Vehicle Number/Name	Driver Name	Vehicle IMEI	First Ignition	Last Ignition	Total Engin ON Time
23	799035		359632109060803	08:00:55	23:25:25	03:51:45
24	782933		354017117817292	08:02:40	17:31:58	00:58:16
25	197098		354017117819439	08:00:45	19:19:53	02:23:03
26	458389		354017117836870	00:17:14	23:59:30	03:10:46
27	537518		354017117442208	08:57:46	18:56:38	05:10:14
28	180751		359633100056113	08:47:39	22:27:57	02:13:18
29	267107		354017117819629	07:58:25	23:15:32	02:29:26
30	556903		354017117817425	08:19:31	17:20:32	00:06:23
31	801474		359632103622129	08:03:22	23:59:51	02:24:31
32	793011		359633100056014	15:46:02	20:40:17	01:27:51
33	790975		354017117833810	02:12:00	21:38:55	05:26:23
34	798970		359633100064935	22:56:44	23:01:58	00:05:02
35	745893		359633100065742	07:48:32	17:10:18	02:30:52
36	813692		354017117833687	08:20:33	18:04:11	01:35:53
37	786836		359633100052328	06:56:28	19:10:37	02:07:17
38	169421		359632109058294	06:54:48	17:33:07	01:01:50
39	170392		354017117442232	09:21:10	19:47:17	05:57:42
40	568501		354017117808150	07:25:22	19:36:00	02:02:16
41	190855		354017117810842	09:18:46	20:03:48	03:33:12
42	189507		354017117834453	06:39:39	19:38:55	03:32:39
43	799034		359632109058310	00:00:01	18:19:58	03:31:57
44	266150		354017117819496	07:32:22	21:40:48	05:14:11
45	572851		354017117804449	08:49:07	15:13:38	03:58:58
46	171364		354017117442240	07:19:02	18:54:52	04:32:03
47	816971		354017117810834	13:41:03	17:16:13	00:16:43
48	816970		359633100064554	07:41:22	21:43:43	02:53:43

**Vehicle Running Report for the date 2021-01-19**

<b>SL NO</b>	<b>Vehicle Number/Name</b>	<b>Driver Name</b>	<b>Vehicle IMEI</b>	<b>First Ignition</b>	<b>Last Ignition</b>	<b>Total Engine ON Time</b>
49	781927		354017117821187	09:05:43	23:31:52	04:53:07
50	793013		359633100057921	17:55:44	21:54:09	01:28:12
51	790976		359633100036206	07:42:43	16:38:43	00:32:20