



CHUBBY CHEEK NURSERY

Vehicle Running Report for the date 2021-08-22

SL NO	Vehicle Number/Name	Driver Name	Vehicle IMEI	First Ignition	Last Ignition	Total Engine ON Time
1	AD-1-87470-MITSUBISHI ROSA		867604055799531	07:10:45	17:28:34	03:54:04
2	AD-2-85577-MITSUBISHI ROSA		867604055806815	02:58:12	16:07:24	04:33:23
3	AD-1-73769-MITSUBISHI ROSA		867604055817515	05:59:16	16:50:46	04:17:06