



CHUBBY CHEEK NURSERY

Vehicle Running Report for the date 2021-10-11

SL NO	Vehicle Number/Name	Driver Name	Vehicle IMEI	First Ignition	Last Ignition	Total Engine ON Time
1	AD-1-87470-MITSUBISHI ROSA		867604055799531	06:35:12	18:26:33	05:19:16
2	AD-2-85577-MITSUBISHI ROSA		867604055806815	00:00:14	15:26:24	05:51:27
3	AD-1-73769-MITSUBISHI ROSA		867604055817515	06:04:31	18:41:10	06:52:11