



## CHUBBY CHEEK NURSERY

Vehicle Running Report for the date 2021-08-06

SL NO	Vehicle Number/Name	Driver Name	Vehicle IMEI	First Ignition	Last Ignition	Total Engine ON Time
1	AD-1-87470-MITSUBISHI ROSA		867604055799531	10:46:40	18:46:20	00:00:02
2	AD-2-85577-MITSUBISHI ROSA		867604055806815	05:41:08	23:15:12	00:40:07