



CHUBBY CHEEK NURSERY

Vehicle Running Report for the date 2021-08-03

SL NO	Vehicle Number/Name	Driver Name	Vehicle IMEI	First Ignition	Last Ignition	Total Engine ON Time
1	AD-1-87470-MITSUBISHI ROSA		867604055799531	03:57:13	20:26:23	05:38:23
2	AD-2-85577-MITSUBISHI ROSA		867604055806815	00:02:29	23:59:02	04:16:32
3	AD-1-73769-MITSUBISHI ROSA		867604055817515	06:07:02	17:48:01	04:17:41