



CHUBBY CHEEK NURSERY

Vehicle Running Report for the date 2021-10-12

SL NO	Vehicle Number/Name	Driver Name	Vehicle IMEI	First Ignition	Last Ignition	Total Engine ON Time
1	AD-1-87470-MITSUBISHI ROSA		867604055799531	06:35:46	19:51:21	04:40:43
2	AD-2-85577-MITSUBISHI ROSA		867604055806815	04:09:29	20:01:56	04:12:25
3	AD-1-73769-MITSUBISHI ROSA		867604055817515	06:06:09	19:14:08	06:08:34