



CHUBBY CHEEK NURSERY

Vehicle Running Report for the date 2021-09-30

SL NO	Vehicle Number/Name	Driver Name	Vehicle IMEI	First Ignition	Last Ignition	Total Engine ON Time
1	AD-1-87470-MITSUBISHI ROSA		867604055799531	01:49:36	21:14:24	03:15:48
2	AD-2-85577-MITSUBISHI ROSA		867604055806815	02:12:15	18:35:20	07:19:14
3	AD-1-73769-MITSUBISHI ROSA		867604055817515	06:08:37	19:20:06	05:12:06