



CHUBBY CHEEK NURSERY

Vehicle Running Report for the date 2021-09-04

SL NO	Vehicle Number/Name	Driver Name	Vehicle IMEI	First Ignition	Last Ignition	Total Engine ON Time
1	AD-1-87470-MITSUBISHI ROSA		867604055799531	06:21:04	18:22:53	00:16:08
2	AD-2-85577-MITSUBISHI ROSA		867604055806815	02:21:52	11:55:42	00:00:00
3	AD-1-73769-MITSUBISHI ROSA		867604055817515	06:33:15	18:03:59	00:25:47