



CHUBBY CHEEK NURSERY

Vehicle Running Report for the date 2021-08-21

SL NO	Vehicle Number/Name	Driver Name	Vehicle IMEI	First Ignition	Last Ignition	Total Engine ON Time
1	AD-1-87470-MITSUBISHI ROSA		867604055799531	09:13:18	18:40:07	00:07:37
2	AD-2-85577-MITSUBISHI ROSA		867604055806815	01:21:01	18:24:41	00:02:44
3	AD-1-73769-MITSUBISHI ROSA		867604055817515	07:00:10	18:43:27	01:40:49