



CHUBBY CHEEK NURSERY

Vehicle Running Report for the date 2021-08-24

SL NO	Vehicle Number/Name	Driver Name	Vehicle IMEI	First Ignition	Last Ignition	Total Engine ON Time
1	AD-1-87470-MITSUBISHI ROSA		867604055799531	07:09:57	16:42:28	03:17:37
2	AD-2-85577-MITSUBISHI ROSA		867604055806815	05:55:21	23:35:10	06:40:26
3	AD-1-73769-MITSUBISHI ROSA		867604055817515	06:05:31	17:59:57	04:16:50