



CHUBBY CHEEK NURSERY

Vehicle Running Report for the date 2021-09-05

SL NO	Vehicle Number/Name	Driver Name	Vehicle IMEI	First Ignition	Last Ignition	Total Engine ON Time
1	AD-1-87470-MITSUBISHI ROSA		867604055799531	06:30:45	18:22:15	05:15:09
2	AD-2-85577-MITSUBISHI ROSA		867604055806815	05:22:09	22:36:15	05:47:32
3	AD-1-73769-MITSUBISHI ROSA		867604055817515	06:05:54	18:12:12	07:44:44