



## CHUBBY CHEEK NURSERY

Vehicle Running Report for the date 2021-08-01

SL NO	Vehicle Number/Name	Driver Name	Vehicle IMEI	First Ignition	Last Ignition	Total Engine ON Time
1	AD-1-87470-MITSUBISHI ROSA		867604055799531	06:36:34	17:24:00	03:05:02
2	AD-2-85577-MITSUBISHI ROSA		867604055806815	00:26:30	20:37:43	07:27:54
3	AD-1-73769-MITSUBISHI ROSA		867604055817515	09:03:56	18:35:00	03:18:20