



CHUBBY CHEEK NURSERY

Vehicle Running Report for the date 2021-09-02

| SL NO | Vehicle Number/Name | Driver Name | Vehicle IMEI | First Ignition | Last Ignition | Total Engine ON Time |
|-------|----------------------------|-------------|-----------------|----------------|---------------|----------------------|
| 1 | AD-1-87470-MITSUBISHI ROSA | | 867604055799531 | 04:38:14 | 15:56:43 | 06:17:00 |
| 2 | AD-2-85577-MITSUBISHI ROSA | | 867604055806815 | 05:17:37 | 18:24:55 | 04:25:53 |
| 3 | AD-1-73769-MITSUBISHI ROSA | | 867604055817515 | 05:55:38 | 19:36:56 | 08:21:57 |