



## CHUBBY CHEEK NURSERY

Vehicle Running Report for the date 2021-09-23

SL NO	Vehicle Number/Name	Driver Name	Vehicle IMEI	First Ignition	Last Ignition	Total Engine ON Time
1	AD-1-87470-MITSUBISHI ROSA		867604055799531	00:36:12	19:06:00	03:10:26
2	AD-2-85577-MITSUBISHI ROSA		867604055806815	01:06:23	17:45:18	02:44:29
3	AD-1-73769-MITSUBISHI ROSA		867604055817515	06:07:53	18:36:23	07:33:41