



## CHUBBY CHEEK NURSERY

Vehicle Running Report for the date 2021-08-09

SL NO	Vehicle Number/Name	Driver Name	Vehicle IMEI	First Ignition	Last Ignition	Total Engine ON Time
1	AD-1-87470-MITSUBISHI ROSA		867604055799531	07:05:47	18:05:25	03:11:39
2	AD-2-85577-MITSUBISHI ROSA		867604055806815	05:57:52	22:49:20	04:42:42
3	AD-1-73769-MITSUBISHI ROSA		867604055817515	00:00:07	18:03:25	05:48:08