



CHUBBY CHEEK NURSERY

Vehicle Activity Report

Reporting Period :2023-09-25 (12 AM -11.59PM)

Generated Date :2023-09-26 7.30 AM

SL NO	Vehicle Number	Vehicle Reg No	Vehicle Imei	Distance	Actual Duty Time(hrs)	Average Speed(Km/hr)	Max Speed(Km/hr)	Actual Running Time(hrs)	Idle Time(hrs)
1	AD-2-85577-MITSUBISHI ROSA	2023-09-25	867604055806815	47.34	13054	9.31	86	11162	1892